

ORIGINAL

Asbestos Survery and Action Plan

5/24/97

1. Fiber Optic pile Ampitheater (amp) Quarry.
Confirmed Asbestos 1 of 1

Fill in hole, Cover and seed. Dispose of excavated material.

2. Ampitheater Quarry base of North face wall.
Confirmed Asbestos 3 of 3

Cover and seed. Wet knock down material on wall. Dispose of excavated material

3. Southeast corner of amp quarry, near storm drain.
Confirmed Asbestos 1 of 2

Cover and seed.

4. West end of fiber optic pile, big rock, South face of Amp Quarry wall.
Confirmed Asbestos 3 of 3

Investigate

5. West bank Amp Quarry.
Confirmed Asbestos 1 of 1

Cover and Seed

5. Silicate bank West of Amp Quarry.
Unconfirmed asbestos

Sample, analyze.

6. Rail bed near County Line Road-Historical bridge area.
Unconfirmed Asbestos

Sample, analyze.

ORIGINAL

Cover and Seed

7. Vistor Center to Amp Quarry trail.
Confirmed Asbestos

Cover and Seed

8. Rail bed near County Line Road-across from split rail fence.
Unconfirmed Asbestos

Terrace cover and seed.

9. Silicate mound-County Line Road
Unconfirmed

Sample and Analyze

10. Old rail bed at County Line Road.
Confirmed

Terrace cover and seed.

11. Rail bed to Keene Quarry
Confirmed Asbestos

Cover and seed

12. Keene Quarry South face.
Confirmed Asbestos

Encapsulate or Terrace.

13. Ditch along beginning of County Line Road
Confirmed Asbestos 1 or 7.

Stone cover, and seed.

14. Cave Quarry
Confirmed Asbestos 8 or 8

Cover and seed